

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

SITE/UNIT FEATURES

Site #	Host Site	Designated Accessible Site?	Accessibility Constraints				Remarks	Spur			Site Signs					Stoves, Grills, Fire Rings and Bear Boxes										Tables				Other							
			Needs Leveling	Obstacles	Excessive Brush/Veg	Inadequate Clear Space		Size	Material	Condition	Remarks	Site Marker	Material	Condition	Other Signage	Material	Condition	Concrete Stove	Steel Stove	Steel Fire Ring	Fire Ring with Steel Grill	HC Fire Ring with Adj. Grill	Ped. Grill	HC Ped Grill	Double Ped. Grill	HC Double Ped Grill	Bear Box	Condition	Remarks	Wood Table (Light)	Wood Table (Heavy)	HC Table (light)	HC Double Table (light)	Condition	Remarks	Remarks	
1		No					Accessible, crushed rock surface	40'	AC		Trailer spur	1								1								Good			1		Good				
2		No					Native surface	40'	AC		Trailer spur	1							1						1		Good/Good		1			Good					
3		No					Native surface	40'	AC		Trailer spur	1							1								Good		1			Good					
4		No					Native surface. Site is almost accessible.	20' x 55'	AC		Long Trailer Spur	1								1					1		Good/Good			1		Good					
5		No					Native surface. Good site to make accessible. Table and spur improvements would make site accessible.	40'	AC		Trailer spur	1								1					1		Good/Good		1			Good					
6		No					Native surface	20' x 50'	AC		Long Trailer Spur	1								1					1		Good			1		Good					
7		No	X				Native surface	40'	AC		Trailer spur	1							1								Good			1		Good					
8		No	X		X		Native surface. Grassy.	40'	AC		Trailer spur	1							1								Good			1		Good					
9		No					Native surface. Trees need to be thinned.	40'	AC		Trailer spur	1								1							Good			1		Good					
10		No					Native surface	40'	AC		Trailer spur	1							1								Good			1		Good					
11		No					Native surface	40'	AC		Trailer spur	1		1					1								Good			1		Good					
12		No					Native surface	20' x 55'	AC		Long Trailer Spur	1								1					1		Good/Good			1		Good					
13		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
14		No					Native surface	20' x 55'	AC		Long Trailer Spur	1								1					1		Good/Good			1		Good					
15		No					Native surface	25'	AC		Car spur	1								1							Good			1		Good					
16		No					Native surface. Site is almost accessible.	40'	AC		Trailer spur	1								1							Good			1		Good					
17		No					Native surface. Walk in site.	25'	AC		Car spur	1								1							Fire pit is brand new.			1		Good		Walk in site.			
18		No					Native surface	40'	AC		Trailer spur	1								1					1		Good/Good			1		Good					
19		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
20		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
21		No					Native surface	25'	AC		Car spur	1								1							Good			1		Good					
22		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
23		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good		Set too low			
24		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
25		No					Native surface	25'	AC		Car spur	1								1							Good			1		Good					
26		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
27		No					Native surface	40'	AC		Trailer spur	1								1							Fire ring is vandalized. Needs to be replaced.			1		Good					
28		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
29		No					Native surface	20' x 55'	AC		Long Trailer Spur	1								1					1		Good/Good			1		Good					
30		No					Native surface	20' x 55'	AC		Long Trailer Spur	1								1							Good			1	1	Good		Double HC table present			
31		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
32		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
33		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
34		No					Native surface	20' x 55'	AC		Long Trailer Spur	1								1							Good			1		Good					
35		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
36		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good		Double HC table present			
37		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
38		No					Native surface/Walk-in site	20' x 55'	AC		Long Trailer Spur	1								1					1		Good			1		Good		Walk in site.			
39		No					Native surface. Accessible except for spur.	36' x 55'	AC		Long Trailer Spur	1								1					1		Good/Good			2	1	Good		Double site.			
40		No					Native surface	20' x 55'	AC		Long Trailer Spur	1								1							Good			1		Good					
41		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
42		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
43		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good		Double site.			
44		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
45		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
46		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
47		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
48		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
49		No					Native surface. Site is accessible.	40'	AC		Trailer spur	1								1							Good			1		Good					
50		No					Native surface	40'	AC		Trailer spur	1								1							Good			1		Good					
51		No					Native surface	25'	AC		Car spur	1								1							Good			1		Good					
52		Yes					Designated accessible site. Crushed rock surface	40' X 16'	AC		Trailer spur	1								1							Good			1		Good					
53		No					Crushed rock surface. Site is accessible	25'	AC		Car spur	1								1							Good			1		Poor		Needs repair.			
54		No					Native surface. Accessible except for rock near grill.	40'	AC		Trailer spur	1								1							Good			1		Good					
Total		1										50								53										10			30	21	6		

**Notes:**