

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

SITE/UNIT FEATURES

| Site # | Host Site | Designated Accessible Site? | Accessibility Constraints | | | | Remarks | Spur | | | | Site Signs | | | | | | Stoves, Grills, Fire Rings and Bear Boxes | | | | | | | | | | Tables | | | | | Other | |
|--------|-----------|-----------------------------|---------------------------|-----------|---------------------|----------------------|--|------|----------|-----------|--------------|-------------|----------|-----------|---------------|----------|-----------|---|-------------|-----------------|----------------------------|------------------------------|------------|--------------|-------------------|---------------------|--|-----------|---------|--------------------|--------------------|--|--|--|
| | | | Needs Leveling | Obstacles | Excessive Brush/Veg | Adequate Clear Space | | Size | Material | Condition | Remarks | Site Marker | Material | Condition | Other Signage | Material | Condition | Concrete Stove | Steel Stove | Steel Fire Ring | Fire Ring with Steel Grill | HC Fire Ring with Adj. Grill | Ped. Grill | HC Ped Grill | Double Ped. Grill | HC Double Ped Grill | Bear Box | Condition | Remarks | Wood Table (Light) | Wood Table (Heavy) | HC Table (light) | | HC Double Table (light) |
| 1 | | No | No | No | No | Yes | Site is entirely accessible but is not designated as handicap accessible. *Needs minor leveling. | NA | NA | NA | Walk-in site | X | PTDF | Good | | | | | 1 | | | | | | 1 | Good/Good | Fire ring is rusted. | | | 1 | | Good | Wood planks on steel base | Accessible path from Site 1 to parking area. |
| 2 | | No | Yes | Yes | Yes | No | Accessible path to site. | NA | NA | NA | Walk-in site | X | PTDF | Good | | | | | 1 | | | | | | 1 | Good/Good | Fire ring is rusted. | | 1 | | Good | | Hazard trees present. Accessible path from Site 2 to parking area. | |
| 3 | | No | No | No | No | Yes | Accessible path to site. | NA | NA | NA | Walk-in site | X | PTDF | Good | | | | | 1 | | | | | | 1 | Good/Good | Fire ring is rusted. | | 1 | | Good | | Accessible path from Site 3 to parking area. | |
| 4 | | No | Yes | Yes | Yes | No | Needs minor leveling. Access to site is difficult | NA | NA | NA | Walk-in site | X | PTDF | Good | | | | | 1 | | | | | | 1 | Poor/Good/Good | Concrete stove is damaged and in poor condition. Fire ring is surrounded in boulders that should be removed. | | 1 | | Good | | | |
| 5 | | No | No | No | No | No | Needs minor leveling. Access to site is difficult | NA | NA | NA | Walk-in site | X | PTDF | Good | | | | | 1 | | | | | | 0 | Good | Bear box is in good condition. Fire ring is rusted. | | 1 | | Fair | Paint is flaking. | | |
| 6 | | No | No | No | No | Yes | Needs minor leveling. Access to site is difficult | NA | NA | NA | Walk-in site | X | PTDF | Good | | | | | 1 | | | | | | 0 | Good/Good | Fire ring is rusted. | 1 | 1 | | Good | Light table is wood plank on steel base. | | |
| 7 | | No | Yes | Yes | No | No | Obstacles present. Needs minor leveling. Access to site is difficult. | NA | NA | NA | Walk-in site | X | PTDF | Good | | | | | 1 | | | | | | 0 | Good* | Fire ring is in good condition but is sitting on rocks. Needs to be reset. | | 1 | | Fair | | Paint is flaking. | |
| 8 | | No | No | Yes | No | Yes | Needs minor leveling. Could be made accessible - Gentle slope, not many obstacles. | NA | NA | NA | Walk-in site | X | PTDF | Good | | | | | 0 | | | | | | 1 | Good/Good | | | 1 | | Good | | | |
| 9 | | No | No | Yes | No | Yes | Needs minor leveling. Could be made accessible - Gentle slope, not many obstacles. | NA | NA | NA | Walk-in site | X | PTDF | Good | | | | | 1 | | | | | | 1 | Good | | | 1 | | Fair | | Table is functional but in need of new paint. Benches are cracked. | |
| 10 | | No | No | Yes | No | Yes | Needs minor leveling. Could be made accessible - Gentle slope, not many obstacles. | NA | NA | NA | Walk-in site | X | PTDF | Good | | | | | 1 | | | | | | 1 | Good | | | 1 | | Good | | | |
| 0 | | 0 | | | | | | | | | | | | | | | | | 10 | | | | | | | | | | | | | | | |

Notes:

- NA - Not applicable.
- HC - Handicap Accessible
- PTDF - Pressure Treated Douglas Fir
- AC - Asphaltic Concrete, otherwise known as asphalt or pavement
- AO - Asphalt Overlay - A top coat of AC applied to a previously paved surface.
- Chip seal - Oil and crushed rock (usually 1/4") applied over a previously paved surface
- Crushed rock - Clean (no fines) crushed rock, usually 1/4" or 3/4"
- Aggregate Base - A combination of crushed rock, sand and clay. The fines make aggregate base compactable.