

**Appendix I-2**  
**Ahart Campground**  
**Photographs**




Photo I-2-1. Entrance/exit area at Ahart Campground. (9/04/08)



Photo I-2-2. Site identification sign at entrance to Ahart Campground. This site is in fair condition due to the large crack. (9/04/08)



**Photo I-2-3. Fee station near entrance to Ahart Campground. Fee tube to right of information board. (9/04/08)**



**Photo I-2-4. Typical site (unit) marker. (9/04/08)**



**Photo I-2-5. Typical parking spur delineated with wood posts and barriers. Note native surface. (9/4/08)**



**Photo I-2-6. Typical site at Ahart Campground. (9/04/08)**



**Photo I-2-7. Concrete and steel stove at site 1, poor condition. (9/04/08)**



**Photo I-2-8. Typical steel fire ring with grill, not accessible. (9/04/08)**



**Photo I-2-9. Typical bear-proof food storage locker (bear box), new and in good condition. (9/04/08)**



**Photo I-2-10. Steel fire ring and grill, poor condition. (9/04/08)**



**Photo I-2-11. Typical heavy wood table showing flaking paint. (9/04/08)**



**Photo I-2-12. Typical heavy wood table with graffiti. (9/04/08)**



**Photo I-2-13. Double-unit, vault toilet building (No. 1). (9/04/08)**



**Photo I-2-14. Dry rot on roof and frame of toilet building No. 1. (9/0408)**



**Photo I-2-15. Toilet building No. 3. (9/04/09)**



**Photo I-2-16. Garbage bins. (9/04/08)**