

Appendix K-1
Lewis Campground
Inventory

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

Name of Facility:	Lewis Campground
Type of Facility:	Campground
Managing Agency:	USDA Forest Service – Tahoe National Forest – Foresthill Ranger District
Date of this Inventory:	September 4, 2008
Inventory Prepared by:	Sandra Walter-Perry (ENTRIX) in consultation with Ed Moore (TNF)

BRIEF DESCRIPTION OF SITE:

Lewis Campground is located at the northeast end of French Meadows Reservoir. It consists of 40 sites, 3 of which are designated as handicap accessible. Each site includes a heavy wood picnic table, a steel fire ring with adjustable grill, and a new, large bear-proof food storage locker (bear box). All sites include a paved parking spur, typically delineated with a combination of wood posts, barrier bars and barrier rocks. Other amenities at this campground include bathrooms with flush toilets, vault toilets, bear-proof garbage containers, and faucets with potable water.

OVERALL CONDITION OF FACILITY:

<p>Condition of Facility: The campground is generally in good condition. The entrance road and loop roads are paved and in good condition. All of the spurs are paved and in good condition, although some are narrow (e.g. < 12 feet). Each site includes a heavy wood table most of which are in good condition, with minor paint flaking on some. Each site includes a large bear box, all in good condition. Each site includes a fire ring with an adjustable fire grill. Most of the fire rings are in good condition but some are set too low, some are set too high, and some are set crooked. In addition, users have surrounded many of the fire rings with rock boulders. One fire ring has a user created rock hearth.</p>
<p>Accessibility Conditions: Three sites (Sites 4, 19, and 21) are designated as handicap accessible and include accessible features such as tables and fire rings. However, the site spurs are too narrow. One bathroom, a double unit structure with flush toilets and sinks was retrofitted to meet accessibility standards. None of the other bathrooms are accessible. None of the water faucets are accessible although one has an accessible handle.</p>
<p>Health and Safety Concerns: None.</p>
<p>Environmental and Cultural Concerns: None</p>
<p>Comments: Water is supplied to this site via the Dolly Creek Water Supply, which is referred to by the Forest Service as the French Meadows North Shore Water System. The water source is a 575 feet deep groundwater well. Flow is approximately 11.75 gallons per minute. Service connections include 11 faucets and 2 bathrooms with flush toilets and sinks.</p>

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

FACILITY FEATURES

Feature	Quantity or Dimensions	Location or Description	Material	Type	Cond	Accessibility						Comments	
						Accessible (yes/no)	Needs Leveling	Obstacles present	Brush or hazard trees	Excessive Slope	Other		
Garbage Containers	6 (2-bin)	Two in front of bathroom # 1, one next to bathroom #. 2, one next to bathroom #2, two next to bathroom # 4	Painted Steel set on concrete pads	Bear-proof	Good	N						X	All of the garbage containers were installed in 1999 and are in good condition. Garbage containers are not considered accessible due to handle design. All are installed on concrete pads.
Trash cans	4	Entrances to male and female sides of bathrooms # 1 and #4	Plastic	Standard trash cans	Good	N						X	Lids are not accessible.
Concrete pads	6	Beneath bear-proof garbage containers	Concrete		Good								
Concrete pads	4	Throughout campground	Concrete		Poor	NA							Broken, out of use.
Bathroom	1 double unit with 2 toilets/urinals and 1 sink per unit	Bathroom # 1, located near entrance to east loop (1-21)	Painted wood	Flush	Good	Y							Converted to be accessible. Good access, no lip at entrance. Freshly painted. Clean interiors.

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

FACILITY FEATURES (continued)

Feature	Quantity or Dimensions	Location or Description	Material	Type	Cond	Accessibility					Comments	
						Accessible (yes/no)	Needs Leveling	Obstacles present	Brush or hazard trees	Excessive Slope		Other
Bathroom	1 double unit with 1 toilet per unit, no sinks	Bathroom #2, located across from Site 12.	Wood	Vault	Good	N						Entrance and stall are too narrow. Poor access. Concrete lip. Exterior condition is good except for roof rot. Interior condition is good.
Bathroom	1 double unit	Bathroom #3, located across from Site 32	Wood	Vault	Good	N						Entrance and stall are too narrow. Poor access. Concrete lip. Exterior condition is good except for roof rot. Interior condition is good.
Bathroom	1 double unit with 2 toilets/urinals and 1 sink per unit	Bathroom # 4, located across from Site 39.	Painted wood	Flush	Good	N						Freshly painted. Clean interiors. Not accessible due to concrete lip and narrow widths. Can be converted to be accessible, like Bathroom #1.

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

FACILITY FEATURES (continued)

Feature	Quantity or Dimensions	Location or Description	Material	Type	Cond	Accessibility						Comments
						Accessible (yes/no)	Needs Leveling	Obstacles present	Brush or hazard trees	Excessive Slope	Other	
Faucets	11	Throughout campground	Standard upright steel pipe mounted to wood post set in corrugated steel drainage sump.		Fair to Good	N	X	X	X	X	X	Accessibility varies. Only one faucet has an accessible handle. Most are difficult to access due to steep grades, unlevel surfaces, and the presence of obstacles. Height of steel sumps varies from below grade to 10 inches high.
Valve Boxes	4	Behind bathrooms 1, 2 and 4 and near tanker fill across from site #40	Plastic or concrete christy boxes		Good	NA						
Fee Tube	1	Adjacent to fee station	Painted steel		Good	Y						
Message box	1	Adjacent to fee station	Painted steel on steel post		Good	Y						
Double Swing gate	1	At entrance	Green painted steel	Swing	Good	NA						New and in excellent condition.
Bar gate?	1	Entrance to loop 1-21, near host site	Green painted steel	Bar	Good							Purpose unknown

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

PARKING, ROADWAYS and TRAVEL PATHS

Feature	Quantity or Dimensions	Location or Description	Material	Cond	Accessibility						Comments
					Accessible (yes/no)	Needs Leveling	Obstacles present	Brush or hazard trees	Excessive Slope	Other	
Access and CG Loop Roads	Approx. 3,115 feet long. 12-24 feet wide.	Main access road, south loop road, north loop return road and north loop road	Pave (AC)	Good	Y						Overall in good condition. See detailed road survey results for additional information.

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

SIGNAGE

Type of Sign	Location	Qt.	Material	Cond	Wording/Graphics	Remarks	Accessibility Notes
Site Identification	Across from entrance to campground on main access road	1	Painted MDO plywood on painted wood posts (24" x 39")	Good	CAMPGROUND Lewis	Sign is functional but split horizontally. Needs to be repaired or replaced.	
Hazard signs	On double gate at entrance	4	Painted aluminum (8" x 24")	Good	Reflective red and silver striping	New	
Traffic	Entrance	1	Painted aluminum sign (18" x 24") on painted PTDF post	Good	SPEED LIMIT 10	New	
Traffic	Exit	1	Painted aluminum sign (18" x 24") on painted PTDF post	Good	OFF HIGHWAY VEHICLES PROHIBITED ON PAVED ROADS	New	
Fee Station	Near entrance to campground	1	Painted MDO plywood board mounted on painted wood crossbars and posts (4' x 8')	Good	SELF-SERVICE PAY STATION plus various informational and regulatory posters	Fee tube and box located in fee station area adjacent to signage.	Fee station is delineated with rock that is level and clear of obstacles. Surface is crushed rock.
Message board	Near entrance to campground	1	Painted MDO plywood board in painted wood frame mounted on painted wood posts (4' x 4')	Fair	MESSAGES	Board is peeling.	
Message board	Adjacent to large message board above	1	Painted plywood on painted wood post.	Fair	none	Needs frame	
Regulatory sign	Loop entrance	1	16" x 50" Al sign on 4"x4" painted wood post	Good	Fee system strictly enforced		

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

SIGNAGE (continued)

Type of Sign	Location	Qt.	Material	Cond	Wording/Graphics	Remarks	Accessibility Notes
Directional	Loop entrance	1	12" x 29" Al sign on 4"x4" painted wood post	Good	1-21 > 22-40 <	Clear protective coating is peeling	
Directional	Loop entrance	1	12" x 12" Al sign on 4"x4" painted wood post	Good	arrow	Clear protective coating is peeling	
Information board	Adjacent to HC bathroom #1, along path	1	Painted MDO on wood posts	Good	Information poster		
Small information board	Adjacent to 9 faucets	9	11" x 18" painted MDO on painted wood post	Good to Poor	No fish cleaning, etc. at faucets	Most are in good condition. Three are in poor condition due to deteriorating wood.	
Directional	Beginning of loop 22-44	1	12" x 12" Al sign on 4"x4" painted wood post	Good	arrow		
Information board	Adjacent to bathroom #4, along path	1	Painted MDO on wood posts	Good	Information poster	Frame is in good condition. Board is peeling eves are peeling.	
Unit Markers	Throughout campground, one at each site	40	PTDF with painted white numbers (4" x 4")	Good	Site numbers		Numbers are painted white for contrast
Handicap Accessible Unit markers	Sites 4, 19, and 21	3	Painted Aluminum mounted to unit marker	Good	ACCESSIBLE with wheelchair symbol	White lettering on blue sign	