

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

SITE/UNIT FEATURES

Site #	Host Site	Designated Accessible Site?	Accessibility Constraints				Remarks	Spur				Site Signs				Stoves, Grills, Fire Rings and Bear Boxes										Tables				Other					
			Needs Leveling	Obstacles	Excessive Brush/Veg	Inadequate Clear Space		Size*	Material	Condition	Remarks	Site Marker	Material	Condition	Other Signage	Material	Condition	Concrete/Steel Stove	Steel Stove	Steel Fire Ring	Fire Ring with Adj. Steel Grill**	HC Fire Ring with Adj. Grill	Ped. Grill	HC Ped Grill	Double Ped. Grill	HC Double Ped Grill	Large Bear Box**	Condition	Remarks		Wood Table (Light)	Wood Table (Heavy)	HC Table (Wood)*	HC Double Table (light)	Condition
1	X		X			X	partly accessible, approach needs leveling, widening	12' x 43'	AC	Good		X	PTDF w/ painted number	Good	Camp host sign	plastic	Good				X-04					X-05	Good/Good	FR set too low		X			Good		
2			X				steep access	10' x 46'	AC	Good	Narrow	X	PTDF w/ painted number	Good						X-04					X-05	Good/Good	FR new but set crooked		X			Good			
3				X			partly accessible, tree roots present	12' x 45'	AC	Good		X	PTDF w/ painted number	Good						X-04					X-05	Good/Good	FR new but surrounded in rock cobbles		X			Good			
4		X					designated accessible site	10' x 37'	AC	Good	Spur not accessible due to narrow width	X	PTDF w/ painted number	Good	HC sign	Painted Al (12" x 18") on wood post	Good			X-98					X-05	Good/Good	good clearer space			X-98		Good			
5			X	X		X		10' x 36'	AC	Good		X	PTDF w/ painted number	Good						X-98					X-05	Good/Good	FR surrounded by rock cobbles		X			Good	Paint flaking		
6			X	X	X		poor site access	12' x 48'	AC	Good		X	PTDF w/ painted number	Good						X-04					X-05	Good/Good	FR surrounded by rock cobbles		X			Good	Set low on one side		
7			X	X	X	X	poor site access, many rocks and debris	10' x 35'	AC	Good		X	PTDF w/ painted number	Good						X-04					X-05	Good/Good	FR new, sloping		X			Good	Sloping		
8			X	X				12' x 40'	AC	Good		X	PTDF w/ painted number	Good						X-04					X-05	Good/Good			X			Good			
9			X	X		X	poor site access	12' x 41'	AC	Good		X	PTDF w/ painted number	Good						X-04					X-05	Good/Good	FR set low, surrounded by rocks		X			Good			
10			X	X		X	poor site access	10' x 35'	AC	Good		X	PTDF w/ painted number	Good						X-04					X-05	Good/Good	FR set low, surrounded by rocks		X			Good			
11			X	X		X	poor site access	10' x 32'	AC	Good		X	PTDF w/ painted number	Good						X-04					X-05	Good/Good	Surrounded by rocks		X			Good			
12			X	X		X	poor site access	12' x 28'	AC	Good		X	PTDF w/ painted number	Good						X-04					X-05	Good/Good	Surrounded by rocks		X			Good			
13			X	X		X	poor site access	12' x 44'	AC	Good		X	PTDF w/ painted number	Good						X-04					X-05	Good/Good			X			Good			
14			X	X		X	poor site access	12' x 44'	AC	Good		X	PTDF w/ painted number	Good						X-04					X-05	Good/Good			X			Good			
15			X	X		X	poor site access	12' x 50'	AC	Good		X	PTDF w/ painted number	Good						X-04					X-05	Good/Good	New, no rocks		X			Good	Table set too low		
16							difficult access but site is partly accessible	12' x 45'	AC	Good		X	PTDF w/ painted number	Good						X-04					X-05	Good/Good	New, no rocks		X			Good			
17			X	X			steep access	12' x 46'	AC	Good		X	PTDF w/ painted number	Good						X-04					X-05	Good/Good	New, no rocks		X			Good			
18			X	X		X	steep access	12' x 22'	AC	Good	Short	X	PTDF w/ painted number	Good						X-04					X-05	Good/Good	New, no rocks		X			Good			
19		X					designated accessible site	12' x 42'	AC	Good	Spur not accessible due to narrow width	X	PTDF w/ painted number	Good	HC sign	Painted Al (12" x 18") on wood post	Good			X-01					X-05	Good/Good	FR rusting			X-01		Good	Paint flaking, area around table is clear with crushed rock surface		
20							partly accessible, could be made fully accessible	12' x 45'	AC	Good		X	PTDF w/ painted number	Good						X-04					X-05	Good/Good			X			Good			
21		X					designated accessible site	16' x 53'	AC	Good		X	PTDF w/ painted number	Good	HC sign	Painted Al (12" x 18") on wood post	Good			X-05		X-98			X-05	Good/Good	FR rusting		X	X-98		Good	Table set too low. Area around table is clear with crushed rock surface.		
22			X	X		X	steep access and rocks	12' x 22'	AC	Good		X	PTDF w/ painted number	Good						X-05					X-05	Good/Good	New, no rocks		X			Good			

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM (continued)

SITE/UNIT FEATURES																																			
Site #	Host Site	Designated Accessible Site?	Accessibility Constraints				Remarks	Spur				Site Signs				Stoves, Grills, Fire Rings and Bear Boxes										Tables				Other					
			Needs Leveling	Obstacles	Excessive Brush/Veg	Inadequate Clear Space		Size*	Material	Condition	Remarks	Site Marker	Material	Condition	Other Signage	Material	Condition	Concrete/Steel Stove	Steel Stove	Steel Fire Ring	Fire Ring with Adj. Steel Grill**	HC Fire Ring with Adj. Grill	Ped. Grill	HC Ped Grill	Double Ped. Grill	HC Double Ped Grill	Large Bear Box**	Condition	Remarks		Wood Table (Light)	Wood Table (Heavy)	HC Table (Wood)*	HC Double Table (light)	Condition
23			X	X		X	obstacles throughout	12' x 43'	AC	Good		X	PTDF w/ painted number	Good					X-98							X-05	Good/Good	New, surrounded by rock cobbles		X			Good		
24			X	X	X	X	obstacles throughout	12' x 44'	AC	Good		X	PTDF w/ painted number	Good					X-05							X-05	Good/Good	New, surrounded by rock cobbles		X			Good	Paint peeling.	
25			X	X	X	X	obstacles throughout	13' x 40'	AC	Good		X	PTDF w/ painted number	Good					X-05							X-05	Good/Good	New		X			Good		
26			X	X		X	poor access	14' x 43'	AC	Good		X	PTDF w/ painted number	Good					X-98							X-05	Good/Good	New, surrounded by rock cobbles		X			Good		
27			X	X		X	poor access	12' x 48'	AC	Good		X	PTDF w/ painted number	Good					X-98							X-05	Good/Good	New, surrounded by rock cobbles		X			Good		
28			X	X	X	X	steep access	10' x 36'	AC	Good		X	PTDF w/ painted number	Good					X-05							X-06	Good/Good	New		X			Good		
29			X	X			steep, long access	12' x 50'	AC	Good		X	PTDF w/ painted number	Good					X-05							X	Good/Good	New		X			Good		
30			X	X			steep access	10' x 42'	AC	Good		X	PTDF w/ painted number	Good					X-98							X	Good/Good	New, surrounded by rock cobbles		X			Good		
31			X	X			steep access	12' x 48'	AC	Good		X	PTDF w/ painted number	Good					X-05							X	Good/Good	New		X			Good		
32			X	X			steep access	10' x 36'	AC	Good		X	PTDF w/ painted number	Good					X-05							X	Good/Good	New, surrounded by rock cobbles		X			Good		
33			X	X		X		12' x 46'	AC	Good		X	PTDF w/ painted number	Good					X-98							X	Good/Good	User created rock hearth.		X			Good		
34			X	X		X	Excessive slope	12' x 28'	AC	Good		X	PTDF w/ painted number	Good					X-05							X	Good/Good			X			Good		
35			X				entrance path too narrow, minor leveling needed, partly accessible	12' x 45'	AC	Good		X	PTDF w/ painted number	Good					X-98							X	Good/Good	New, surrounded by rock cobbles		X			Good	Paint peeling.	
36			X	X		X	steep entry	12' x 45'	AC	Good		X	PTDF w/ painted number	Good					X-98							X	Good/Good	New, surrounded by rock cobbles		X			Good		
37			X	X	X	X	steep entry	10' x 28'	AC	Good		X	PTDF w/ painted number	Good					X-05							X	Good/Good			X			Good	Sloping	
38			X	X			steep entry, minor leveling needed, minor obstacles, partly accessible	12' x 50'	AC	Good		X	PTDF w/ painted number	Good					X-98							X	Good/Good	New, surrounded by rock cobbles		X			Good		
39			X	X	X	X	poor access, steep	10' x 30'	AC	Good		X	PTDF w/ painted number	Good					X-05							X	Good/Good			X			Good		Poor drainage towards site.
40			X				insufficient clear space due to tables, minor leveling needed, partly accessible	12' x 50'	AC	Good		X	PTDF w/ painted number	Good					X-98							X	Good/Good	New, surrounded by rock cobbles		X			Good		
1		3										40							1	37	2	1				40				37	3				

Notes:

- designated handicap accessible site
- \* - dimensions based on information provided by Ed Moore, TNF
- \*\* - presence and year installed based on information provided by Ed Moore, TNF
- NA - Not applicable.
- HC - Handicap Accessible
- PTDF - Pressure Treated Douglas Fire
- AC - Asphaltic Concrete, otherwise known as asphalt or pavement
- AO - Asphalt Overlay - A top coat of AC applied to a previously paved surface.
- Chip seal - Oil and crushed rock (usually 1/4") applied over a previously paved surface
- Crushed rock - Clean (no fines) crushed rock, usually 1/4" or 3/4"
- Aggregate Base - A combination of crushed rock, sand and clay. The fines make aggregate base compactable.