

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

SITE/UNIT FEATURES

Site #	Host Site	Designated Accessible Site?	Accessibility Constraints				Spur				Site Signs						Stoves, Grills, Fire Rings and Bear Boxes										Tables				Other					
			Needs Leveling	Obstacles	Excessive Brush/Veg	Inadequate Clear Space	Remarks	Size*	Material	Condition	Remarks	Site Marker	Material	Condition	Other Signage	Material	Condition	Concrete/Steel Stove	Steel Stove	Steel Fire Ring	Fire Ring with Steel Grill**	HC Fire Ring with Adj. Grill	Ped. Grill	HC Ped Grill	Double Ped. Grill	HC Double Ped Grill	Large Bear Box**	Condition	Remarks	Wood Table (Light)	Wood Table (Heavy)	HC Table (light)	HC Double Table (light)	Condition	Remarks	Remarks
1		No	X	X		X	9' x 35'	Native	Good	6 barrier posts + 4 barrier bars (1 is broken, needs repair)	1	Redwood stained PTDf with painted white lettering.	Good	None						X-98						X-06	Poor/good/good	Stove is damaged. Fire ring is in good condition but set too low. BB is new and in good condition.		1			good	Paint flaking.	Fire ring installed in 1998. Bear boxes installed in 2006.	
2		No	X			X	10' x 35'	Native	Good	2 barrier posts+ 4 barrier bars	1	Stained PTDf	Good	None						X-98						X-06	good/good	Fire ring is surrounded by rocks. BB is new and in good condition.		1			fair	Paint flaking, graffiti.	Fire ring installed in 1998. Bear boxes installed in 2006.	
3		No	X				10' x 41'	Native	Good	7 barrier psots + 2 barrier bars	1	Stained PTDf	Good	None						X-98						X-06	fair/good	Stove is damaged. Fire ring is surrounded by rocks. BB is new and in good		1			fair	paint flaking, graffiti, boards splitting.	Fire ring installed in 1998. Bear boxes installed in 2006.	
4		No	X				14' x 31'	Native	Good	8 barrier posts + 2 barrier bars + 3 barrier rocks	1	Stained PTDf	Good	None						X-98						X-06	fair/good	Grill is bent. Bear box is new and in good condition.		2			fair	paint flaking, graffiti.	Fire ring installed in 1998. Bear boxes installed in 2006.	
5		No	X				16' x 41'	Native	Good	6 barrier posts, 2 barrier bars, 3 barrier rocks	1	Stained PTDf	Good	None						X-98						X-06	good/good	Grill surrounded by rock. BB is new and in good condition.		0				table missing, moved to site 4	Fire ring installed in 1998. Bear boxes installed in 2006.	
6		No	X				10' x 45'	Native	Good	5 posts, 3 bars	1	Stained PTDf	Good	None						X-98						X-06	fair/good	Grill bent, ring bent. BB new and good.		1			good	paint flaking	Fire ring installed in 1998. Bear boxes installed in 2006.	
7		No	X			X	10' x 34'	Native	Good	7 posts, 2 bars	1	Stained PTDf	Good	None						X-98						X-06	fair/good	ring bent, surrounded by rocks. Grill is in good condition. BB new and good.		1			fair	paint flaking, graffiti, set too low	Fire ring installed in 1998. Bear boxes installed in 2006.	
8		No	X				10' x 30'	Native / cobbles	Good	1 post + 8 rock	1	Stained PTDf	Good	None						X-98						X-06	fair/good	Grill bent, ring bent. BB new and good.		1			fair	paint flaking, minor graffiti	Fire ring installed in 1998. Bear boxes installed in 2006.	
9		No	X	X			10' x 40'	Native	Good	10 rock barriers, 2 bars.	1	Stained PTDf	Good	None						X-98						X-06	good/good	Ring is surrounded by rocks. BB new and good.		1			fair	paint flaking, minor graffiti, benches splitting	Fire ring installed in 1998. Bear boxes installed in 2006.	
10		No	X	X			13' x 42'	Native	Good	7 rock barriers, 3 posts, 1 bar	1	Stained PTDf	Good	None						X-98						X-06	good/good	Ring is surrounded by rocks. BB new and good.		1			fair	paint flaking, minor graffiti	Fire ring installed in 1998. Bear boxes installed in 2006.	
11		No	X	X		X	12' x 44'	Native	Good	4 barrier bars, 3 rocks	1	Stained PTDf	Good	None						X-98						X-06	good/good	Ring is surrounded by rocks. BB new and good.		1			good		Fire ring installed in 1998. Bear boxes installed in 2006.	
12		No	X	X			10' x 47'	Native	Good	5 bars, 3 rocks	1	Stained PTDf	Good	None						X-98						X-06	good/good	Ring is surrounded by rocks. BB new and good.		1			fair	paint flaking.	Fire ring installed in 1998. Bear boxes installed in 2006.	
		0									12									12						12										

Notes:

- \* - dimensions based on information provided by Ed Moore , TNF
- \*\* - presence and year installed based on information provided by Ed Moore, TNF
- NA - Not applicable.
- HC - Handicap Accessible
- PTDF - Pressure Treated Douglas Fir
- AC - Asphaltic Concrete, otherwise known as asphalt or pavement
- AO - Asphalt Overlay - A top coat of AC applied to a previously paved surface.
- Chip seal - Oil and crushed rock (usually 1/4") applied over a previously paved surface
- Crushed rock - Clean (no fines) crushed rock, usually 1/4" or 3/4"
- Aggregate Base - A combination of crushed rock, sand and clay. The fines make aggregate base compactable.