

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

SITE/UNIT FEATURES

Site #	Host Site	Designated Accessible Site?	Accessibility Constraints				Spur				Site Signs				Stoves, Grills, Fire Rings and Bear Boxes											Tables				Other Remarks					
			Needs Leveling	Obstacles	Excessive Brush/Veg	Inadequate Clear Space	Remarks	Size* (feet)	Material	Condition	Remarks	Site Marker	Material	Condition*	Other Signage	Material	Condition	Concrete Stove**	Steel Stove	Fire Ring**	Fire Ring with Adj. Steel Grill**	HC Fire Ring with Adj. Grill**	Ped. Grill**	HC Ped Grill	Double Ped. Grill	Small Bear Box**	Large Bear Box**	Condition	Remarks**		Wood Table (Light)	Wood Table (Heavy)	HC Table (Wood)**	HC Double Table (light)	Condition
1			X				10 x 38			Narrow	X	PTDF	All site markers were recently installed and are in excellent condition.							X - 03							X - 03	Good/Good	All bear boxes are relatively new and in good condition.		X			Good	All tables are generally in good condition, but many have flaking paint.
2			X				10 x 64			Narrow	X	PTDF	Good						X - 03							X - 03	Good/Good			X		Good			
3	X		X				10 x 46			Narrow	X	PTDF	Good			X - 66		X - 66									Good/Good			X		Good			
4			X				11 x 42			Narrow	X	PTDF	Good						X - 98							X - 03	Good/Good			X		Good			
5			X				10 x 42			Narrow	X	PTDF	Good						X - 98							X - 03	Good/Good			X		Good			
6			X				10 x 48			Narrow	X	PTDF	Good						X - 98							X - 03	Good/Good			X		Good			
7			X				10 x 38			Narrow	X	PTDF	Good						X - 98							X - 03	Good/Good			X		Good			
8			X				10 x 48			Narrow	X	PTDF	Good						X - 98							X - 03	Good/Good			X		Good			
9			X				10 x 55			Narrow	X	PTDF	Good							X - 01						X - 03	Good/Good			X		Good			
10			X				10 x 42			Narrow	X	PTDF	Good							X - 01						X - 03	Good/Good			X		Good			
11			X				10 x 46			Narrow	X	PTDF	Good							X - 01						X - 03	Good/Good			X		Good			
12			X				10 x 50			Narrow	X	PTDF	Good						X - 01							X - 03	Good/Good			X		Good			
13			X				10 x 45			Narrow	X	PTDF	Good							X - 01						X - 03	Good/Good			X		Good			
14			X				10 x 42			Narrow	X	PTDF	Good						X - 01					X - 02			Good/Good			X		Good			
15			X				10 x 46			Narrow	X	PTDF	Good						X - 01					X - 02			Good/Good			X		Good			
16		X					14 x 54				X	PTDF	Good	HC site sign	Painted Al mounted on site marker	Good				X - 01					X - 02		Good/Good				X - 01		Good		
17		X					14 x 54				X	PTDF	Good	HC site sign	Painted Al mounted on site marker	Good			X - 97		X - 97				X - 02		Good/Good/Good				X - 97		Good		

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM (continued)

SITE/UNIT FEATURES

Site #	Host Site	Designated Accessible Site?	Accessibility Constraints				Spur				Site Signs				Stoves, Grills, Fire Rings and Bear Boxes										Tables				Other								
			Needs Leveling	Obstacles	Excessive Brush/Veg	Inadequate Clear Space	Remarks	Size* (feet)	Material	Condition	Remarks	Site Marker	Material	Condition*	Other Signage	Material	Condition	Concrete Stove**	Steel Stove	Fire Ring**	Fire Ring with Adj. Steel Grill**	HC Fire Ring with Adj. Grill**	Ped. Grill**	HC Ped Grill	Double Ped. Grill	Small Bear Box**	Large Bear Box**	Condition	Remarks**	Wood Table (Light)	Wood Table (Heavy)	HC Table (Wood)**	HC Double Table (light)	Condition	Remarks**	Remarks	
18		X					14 x 45				X	PTDF	Good	HC site sign	Painted Al mounted on site marker	Good					X - 01							X - 02		Good/Good				X - 01		Good	
19			X				10 x 46			Narrow	X	PTDF	Good								X - 02						X - 02		Good/Good				X		Good		
20			X				10 x 40			Narrow	X	PTDF	Good								X - 98						X - 02		Good/Good				X		Good		
21			X				10 x 35			Narrow	X	PTDF	Good								X - 02						X - 02		Good/Good				X		Good		
22			X				10 x 50			Narrow	X	PTDF	Good								X - 98						X - 02		Good/Good				X		Good		
23			X				11 x 36			Narrow	X	PTDF	Good								X - 98						X - 02		Good/Good				X		Good		
24			X				10 x 36			Narrow	X	PTDF	Good								X - 98						X - 02		Good/Good				X		Good		
25			X				10 x 47			Narrow	X	PTDF	Good								X - 01						X - 02		Good/Good				X		Good		
26			X				10 x 48			Narrow	X	PTDF	Good								X - 98						X - 02		Good/Good				X		Good		
27			X				10 x 40			Narrow	X	PTDF	Good								X - 00						X - 02		Good/Good				X		Good		
28			X				10 x 46			Narrow	X	PTDF	Good								X - 00						X - 02		Good/Good				X		Good		
29			X				10 x 41			Narrow	X	PTDF	Good								X - 03					X - 03		Good/Good				X		Good			
30			X				10 x 47			Narrow	X	PTDF	Good								X - 00						X - 03		Good/Good				X		Good		
31			X				10 x 45			Narrow	X	PTDF	Good								X - 00						X - 03		Good/Good				X		Good		
32	X		X				10 x 38			Narrow	X	PTDF	Good								X - 03						X - 03		Good/Good				X		Good		
33			X				10 x 44			Narrow	X	PTDF	Good								X - 03						X - 03		Good/Good				X		Good		
34			X				10 x 38			Narrow	X	PTDF	Good								X - 03						X - 03		Good/Good				X		Good		
35			X				10 x 40			Narrow	X	PTDF	Good								X - 98						X - 03		Good/Good				X		Good		

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM (continued)

SITE/UNIT FEATURES

Site #	Host Site	Designated Accessible Site?	Accessibility Constraints				Remarks	Spur				Site Signs						Stoves, Grills, Fire Rings and Bear Boxes											Tables				Other Remarks								
			Needs Leveling	Obstacles	Excessive Brush/Veg	Inadequate Clear Space		Size* (feet)	Material	Condition	Remarks	Site Marker	Material	Condition*	Other Signage	Material	Condition	Concrete Stove**	Steel Stove	Fire Ring**	Fire Ring with Adj. Steel Grill**	HC Fire Ring with Adj. Grill**	Ped. Grill**	HC Ped Grill	Double Ped. Grill	Small Bear Box**	Large Bear Box**	Condition	Remarks**	Wood Table (Light)	Wood Table (Heavy)	HC Table (Wood)**		HC Double Table (light)	Condition	Remarks**					
36		X						13 x 45					X	PTDF	Good	HC site sign	Painted Al mounted on site marker	Good									X - 01							X - 03	Good/Good				X - 01	Good	
37			X					10 x 56				Narrow	X	PTDF	Good												X - 03							X - 04	Good/Good			X		Good	
38		X						11 x 47					X	PTDF	Good	HC site sign	Painted Al mounted on site marker	Good									X - 01							X - 04	Good/Good				X - 01	Good	
39			X					10 x 42				Narrow	X	PTDF	Good												X - 03							X - 04	Good/Good			X		Good	
40			X					10 x 45				Narrow	X	PTDF	Good												X - 01							X - 04	Good/Good			X		Good	
41			X					10 x 44				Narrow	X	PTDF	Good												X - 98							X - 04	Good/Good			X		Good	
42			X					11 x 48				Narrow	X	PTDF	Good												X - 98							X - 04	Good/Good			X		Good	
43			X					10 x 46				Narrow	X	PTDF	Good												X - 03							X - 04	Good/Good			X		Good	
44			X					10 x 35				Narrow	X	PTDF	Good												X - 00							X - 04	Good/Good			X		Good	
45			X					10 x 48				Narrow	X	PTDF	Good												X - 98							X - 04	Good/Good			X		Good	
46			X					10 x 30				Narrow	X	PTDF	Good												X - 98							X - 04	Good/Good			X		Good	
47			X					10 x 33				Narrow	X	PTDF	Good												X - 03							X - 04	Good/Good			X		Good	
48			X					10 x 48				Narrow	X	PTDF	Good												X - 03							X - 04	Good/Good			X		Good	
49			X					20 x 34					X	PTDF	Good												X - 98							X - 04	Good/Good			X		Good	
50			X					10 x 44				Narrow	X	PTDF	Good												X - 98							X - 04	Good/Good			X		Good	
51			X					10 x 30				Narrow	X	PTDF	Good												X - 98							X - 04	Good/Good			X		Good	
52			X					10 x 44				Narrow	X	PTDF	Good												X - 98							X - 04	Good/Good			X		Good	
53			X					10 x 50				Narrow	X	PTDF	Good												X - 98							X - 04	Good/Good			X		Good	

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM (continued)

SITE/UNIT FEATURES

Site #	Host Site	Designated Accessible Site?	Accessibility Constraints				Spur				Site Signs						Stoves, Grills, Fire Rings and Bear Boxes											Tables				Other							
			Needs Leveling	Obstacles	Excessive Brush/Veg	Inadequate Clear Space	Remarks	Size* (feet)	Material	Condition	Remarks	Site Marker	Material	Condition*	Other Signage	Material	Condition	Concrete Stove**	Steel Stove	Fire Ring**	Fire Ring with Adj. Steel Grill**	HC Fire Ring with Adj. Grill**	Ped. Grill**	HC Ped Grill	Double Ped. Grill	Small Bear Box**	Large Bear Box**	Condition	Remarks**	Wood Table (Light)	Wood Table (Heavy)	HC Table (Wood)**	HC Double Table (light)	Condition	Remarks**	Remarks			
54			X							10 x 38			Narrow	X	PTDF	Good				X - 98							X - 04	Good/Good						X			Good		
55			X							10 x 38			Narrow	X	PTDF	Good				X - 98							X - 04	Good/Good						X			Good		
56			X							10 x 33			Narrow	X	PTDF	Good				X - 03							X - 04	Good/Good						X			Good		
57			X							10 x 52			Narrow	X	PTDF	Good				X - 03							X - 04	Good/Good						X			Good		
58			X							10 x 32			Narrow	X	PTDF	Good				X - 03							X - 04	Good/Good						X			Good		
59			X							10 x 33			Narrow	X	PTDF	Good				X - 98							X - 04	Good/Good						X			Good		
60			X							10 x 40			Narrow	X	PTDF	Good				X - 98							X - 04	Good/Good						X			Good		
61			X							10 x 48			Narrow	X	PTDF	Good				X - 98							X - 04	Good/Good						X			Good		
62		X								10 x 48				X	PTDF	Good	HC site sign	Painted Al mounted on site marker	Good			X - 01						X - 04	Good/Good						X - 01			Good	
63		X								11 x 52				X	PTDF	Good	HC site sign	Painted Al mounted on site marker	Good			X - 01						X - 05	Good/Good						X - 01			Good	
64		X								20 x 48				X	PTDF	Good	HC site sign	Painted Al mounted on site marker	Good			X - 01						X - 05	Good/Good						X - 01			Good	
65			X							10 x 30				X	PTDF	Good				X - 98							X - 05	Good/Good						X			Good		
66			X							10 x 42				X	PTDF	Good				X - 98							X - 05	Good/Good						X			Good		
67			X							10 x 39				X	PTDF	Good				X - 98							X - 05	Good/Good						X			Good		
68			X							10 x 48				X	PTDF	Good				X - 98							X - 05	Good/Good						X			Good		
69			X							10 x 45				X	PTDF	Good				X - 03							X - 05	Good/Good						X			Good		
70			X							11 x 28				X	PTDF	Good				X - 05							X - 05	Good/Good						X			Good		
71			X							10 x 46				X	PTDF	Good				X - 05							X - 05	Good/Good						X			Good		

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM (continued)

SITE/UNIT FEATURES

Site #	Host Site	Designated Accessible Site?	Accessibility Constraints				Spur				Site Signs						Stoves, Grills, Fire Rings and Bear Boxes										Tables					Other			
			Needs Leveling	Obstacles	Excessive Brush/Veg	Inadequate Clear Space	Remarks	Size* (feet)	Material	Condition	Remarks	Site Marker	Material	Condition*	Other Signage	Material	Condition	Concrete Stove**	Steel Stove	Fire Ring**	Fire Ring with Adj. Steel Grill**	HC Fire Ring with Adj. Grill**	Ped. Grill**	HC Ped Grill	Double Ped. Grill	Small Bear Box**	Large Bear Box**	Condition	Remarks**	Wood Table (Light)	Wood Table (Heavy)	HC Table (Wood)**	HC Double Table (light)	Condition	Remarks**
72			X								X	PTDF	Good						X - 05							X - 05	Good/Good			X				Good	
73			X								X	PTDF	Good						X - 05							X - 05	Good/Good			X				Good	
74			X								X	PTDF	Good						X - 05							X - 05	Good/Good			X				Good	
75			X								X	PTDF	Good						X - 05							X - 05	Good/Good			X				Good	
	2	8									75			8				1		2	61	12				15	59			67	8				

Notes:

- designated handicap accessible site
- * - dimensions based on information provided by Ed Moore, TNF
- ** - presence and year installed based on information provided by Ed Moore, TNF
- NA - Not applicable.
- HC - Handicap Accessible
- PTDF - Pressure Treated Douglas Fire
- AC - Asphaltic Concrete, otherwise known as asphalt or pavement
- AO - Asphalt Overlay - A top coat of AC applied to a previously paved surface.
- Chip seal - Oil and crushed rock (usually 1/4") applied over a previously paved surface
- Crushed rock - Clean (no fines) crushed rock, usually 1/4" or 3/4"
- Aggregate Base - A combination of crushed rock, sand and clay. The fines make aggregate base compactable.