

Appendix J-2
French Meadows Campground
Photographs



Photo J-2-1. Site Identification sign, good condition. (7/24/08)



Photo J-2-2. Signage at French Meadows Campground exit. (7/24/08)



Photo J-2-3. Fee station at French Meadows Campground. (7/24/08)



Photo J-2-4. Swing gate and regulatory sign at start of east loop road identifying Sites 1-31 as reservable sites. (7/24/08)



Photo J-2-5. Swing gate and east loop entrance road. The gate was installed in September 2002. Site 2 is in center of photograph. (7/24/08)



Photo J-2-6. Regulatory sign at start of west loop. (7/24/08)



Photo J-2-7. Typical site marker. (7/24/08)



Photo J-2-8. Information board. (7/24/08)



Photo J-2-9. Typical water faucet and information board. Faucet is not accessible. (7/24/08)



Photo J-2-10. Wood bathrooms with have flush toilets and sinks, converted to be accessible. Note accessible pathway. (7/24/08)



Photo J-2-11. Typical handicap accessible site sign. (7/24/08)



Photo J-2-12. Accessible fire ring with adjustable grill. (7/24/08)



Photo J-2-13. Example accessible wood picnic table. (7/24/08)



Photo J-2-14. Example double unit wood bathroom #3, not accessible. (7/24/08)



Photo J-2-15. Inside of bathroom #3. (7/24/08)



Photo J-2-16. Bear-proof recycling container. (7/24/08)



Photo J-2-17. Typical bear-proof garbage container and water faucet. Bathroom #6 in background. (7/24/08)



Photo J-2-18. Typical bear-proof food storage locker (bear box) on concrete pad. (7/24/08)