

Appendix K-2
Lewis Campground
Photographs



Photo K-2-1. Site Identification sign, good condition. (9/04/08)



Photo K-2-2. Signage at Lewis Campground exit, good condition. (9/04/08)



Photo K-2-3. Swing gate with reflective hazard signs located at entrance to Lewis Campground, good condition. (9/04/08)



Photo K-2-4. Fee station at Lewis Campground located near entrance, all in good condition. (9/04/08)



Photo K-2-5. Site 1, Campground host site. (9/4/08)



Photo K-2-6. Paved accessible pathway to accessible bathroom with information board, adjacent to host site. All in good condition. (9/04/08).




Photo K-2-7. Typical non-accessible campsite. (9/04/08)



Photo K-2-8. Typical water faucet and information board located along loop roads, not accessible. (9/04/08)



Photo K-2-9. Typical 2-bin, bear-proof garbage container, new and in good condition. Note water faucet and information board on right side of photograph. Faucet is not accessible. (9/04/08)



Photo K-2-10. Wood bathroom structure No. 2. This is a double unit vault toilet in fair condition. Not accessible. (9/04/08)



Photo K-2-11. Dry rot on bathroom structure No. 2. (9/04/08)



Photo K-2-12. Wood bathroom structure with flush toilets and sinks, not accessible. (9/04/08)



Photo K-2-13. Sinks inside of wood bathroom. (9/04/08)



Photo K-2-14. Stalls inside of wood bathroom. These stalls are not accessible but this type of bathroom can be converted to meet accessibility standards. (9/04/08)



Photo K-2-15. Faucet with accessible handle. (9/04/09)



Photo K-2-16. Bear-proof garbage bins on concrete pads. Wood bathroom structure in background has flush toilets and has been converted to meet accessibility standards. (9/04/08)



Photo K-2-17. Accessible approach to bathroom. Note the absence of level changes. (9/04/08)



Photo K-2-18. Inside of wood bathroom structure converted to meet accessibility standards. (9/04/08)



Photo K-2-19. Designated accessible camp site. This type of sign is also present at Sites 4 and 19. (9/04/08)



Photo K-2-20. Accessible heavy wood table and pedestal grill at accessible Site 21. Note clear space around table and level, crushed rock surface. (9/04/08)