DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

SITE/UNIT FEATURES

			Accessibility Constraints					Spur				Site Signs						Stoves, Grills, Fire Rings and Bear Boxes													Tables						Other
Site #	Host Site	Designated Accessible Site?	Needs Leveling	Obstacles	Excessive Brush/Veg	Inadequate Clear Space	Remarks	Size	Material	Condition	Remarks	Site Marker	Material	Condition	Other Signage	Material	Condition	Concrete Stove w/ Steel Grill	Steel Stove	Steel Fire Ring	Fire Ring with Steel Grill	HC Fire Ring with Adj. Grill	Ped. Grill	HC Ped Grill	Double Ped. Grill	HC Double Ped Grill	Bear Box	Condition	Remarks	Wood Table (Light)	Wood Table (Heavy)	HC Table (light)	HC Double Table (light)	Condition	Remarks	Remarks
1		No	Yes	Yes				NA	NA	NA	Hike-in/ Boat-in Site	X	Carsonite Marker on Trail (#1/2)	Good				1											Concrete grill has user created rock extension		1			Fair		
2		No	Yes	Yes		Yes		NA	NA	NA	Hike-in/ Boat-in Site	X	Carsonite Marker on Trail (#1/2)	Good				1										Fair	Concrete grill is damage on ends and has user created rock extension		1			Fair	Grafitti, splits bench boards	
3		No	Yes	Yes				NA	NA	NA	Hike-in/ Boat-in Site	X	Carsonite Marker on Trail (#3)	Good				1											Concrete grill has user created rock extension		1			Fair		
4		No	Yes	Yes	Yes	Yes	Lots of large rocks and forest debris, including large rallen tree stumps.	NA	NA	NA	Hike-in/ Boat-in Site	X	Carsonite Marker on Trail (#4)	Good				1										Good	Large user created rock ring extention on concrete grill but concrete and grill are undamaged.		1			Fair	Many obstacles (large rocks) and bruch around table. Table is set crooked and too low on one side.	
5		No	Yes	Yes				NA	NA	NA	Hike-in/ Boat-in Site	X	Carsonite Marker on Trail (#5/6)	Good				1										Fair			1			Good	Paint peeling	Abaondoned homeless camp. Lots of litter.
6		No	Yes	Yes			Lots of small forest debris and rocks.	NA	NA	NA	Hike-in/ Boat-in Site	X	Carsonite Marker on Trail (#5/6)	Good				1										Good	User created rock ring extention on concrete grill but concrete and grill are undamaged.		1			Good	Paint peeling	
7		No	Yes	Yes			Boulder and vegetation around grill.	NA	NA	NA	Hike-in/ Boat-in Site	X	Carsonite Marker on Trail (#7)	Good				1										Good	Does not appear to be heavily used.		1			Poor	Table boards are badly damaged. Table is set too low.	
8		No	Yes	Yes			Relatively flat and clear around table. Large trees around grill.	NA	NA	NA	Hike-in/ Boat-in Site	X	Carsonite Marker on Trail (#8/9)	Good				1										Good	Does not appear to be heavily used.		1			Fair	Peeling pain, cracked bench boards.	
9		No	Yes	Yes	Yes	Yes	Lots of forest debris, large and small. Large rocks and boulders.	NA	NA	NA	Hike-in/ Boat-in Site	X	Carsonite Marker on Trail (#8/9)	Good				1										Good	Does not appear to be heavily used.		1			Good	Large rock adjacent to table. Lots of Forest debris around table. Site does not appear to be used.	
10		No	Yes	Yes			Lots of large rocks and forest debris, including large rallen tree stumps.	NA	NA	NA	Hike-in/ Boat-in Site	No						1										Good	User created rock ring extention on concrete grill but concrete and grill are undamaged.		1			Good	Flaking paint. Rock ring extend to under table, impeding access to table.	
11		No	Yes	Yes	Yes	Yes	Trail to site is unmarked and almost impossible to find. Very steep and undefined.	NA	NA	NA	Hike-in/ Boat-in Site	No						1										Good			1			Poor	Table is severly damaged and set so low that the bench boards are on the ground.	Site is almost impossible to find. Does not appear to be used at all. Heavy forest debris, including large fallen limbs.
12		No	Yes	Yes	Yes	Yes	Trail to site is unmarked and almost impossible to find. Very steep and undefined.	NA	NA	NA	Hike-in/ Boat-in Site	No						1										Good	Does not appear to be used. Ferns growing into grill.		1			Good	Stack of large limbs next to table. Lots of ferns growing around table suggesting no recent use.	Site is almost impossible to find. Does not appear to be used at all. Heavy forest debris, including large fallen limbs.
		0										**9**						**12**													**12**					

Notes:

NA - Not applicable.
HC - Handicap Accessible
PTDF - Pressure Treated Doulas Fire
AC - Asphaltic Concrete, otherwise known as asphalt or pavement
AO - Asphalt Overlay - A top coat of AC applied to a previously paved surface.
Chip seal - Oil and crushed rock (usually 1/4") applied over a previously paved surface
Cruhsed rock - Clean (no fines) crushed rock, usually 1/4" or 3/4"
Aggregate Base - A combination of crushed rock, sand and clay. The fines make aggregate base compactable.