

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

SITE/UNIT FEATURES

Site #	Host Site	Designated Accessible Site?	Accessibility Constraints				Remarks	Spur		Site Signs				Tables												Other Remarks										
			Needs Leveling	Obstacles	Excessive Brush/Veg	Inadequate Clear Space		RV	Regular	Material	Condition/Remarks	Site Marker	Material	Condition	Remarks	Group Fire Ring**	Condition/Remarks	Old Benches**	Condition/Remarks	New Benches**	Condition/Remarks	Double Ped. Grill**	Condition/Remarks	Fire Pit	Condition/Remarks		Large Bear Box**	Condition/Remarks	Bear-proof Garbage**	Condition/Remarks	Garbage Cans	Condition/Remarks	Serving Table (Heavy Wood)**	Condition	Picnic Table (Heavy Wood)**	Condition
Brush Wolf (25 person site)																																				
		No	X	X			Relatively level. Need minor leveling and removal of small obstacles. Good clearance around site features.	4	4	Paved and striped with barrier posts around edges	Good Striping is fading. Barrier posts are in good condition.	X	Aluminum on PTDF post	Fair	Bent	1-1966	Good Surrounded by rock ring	5-1966	Fair to poor set too low, need sanding and painting	5-2006	Good Heavy wood benches on steel posts set in ground	1-2001	Good			2-2002	Good 1 is set on concrete pad, the other is not	2-1999	Good Both are set on concrete pads	1	fair	3	Good	4	Good, except for one which is broken	
Little Wolf (25 person site)																																				
		No	X	X			Relatively level. Three steps from parking area to campsite - not accessible	4	6	Paved and striped with barrier posts around edges	Good Some striping is faded. Barrier posts are in good condition	X	Aluminum on PTDF post	Good		1-1966	Good Surrounded by rock ring		5-2006	Good Heavy wood benches on steel posts set in ground	1-2002	Good			2-2002	Good. Both are set on concrete pads.	2-1999	Good			3	Good	4	Good		
Prairie Wolf (25 person site)																																				
		No	X	X			Lots of rocks and bedrock obstruct all travel paths around site. This site would be very difficult to make accessible.	2	7	Paved and striped with barrier posts, bars, and rocks around edges.	Good Barrier posts and bars are in good condition. Individual stalls are narrow.	X	Aluminum on PTDF post	Good		1-1966	Fair Ring is made of corrugated steel set about 16 inches above grade.	5-1966	Fair Old style benches. Not accessible. Limited clear space. Need sanding and painting. One is not near fire ring.			1-2002	Good			2-2002	Good. Both are set on concrete pads.	2-1999	Good			3	Good	4	Good	According to Ed Moore, it is not possible to install new benches around fire ring at this site because the soil horizon is thin. That is, there is bedrock immediately below the surface.
Black Bear (50 person site)																																				
		No	X	X	X	X	Sight is relatively flat but needs minor leveling and removal of obstacles. Overgrown brush (mainly grasses) throughout campground. Many tables impede movement through kitchen area. Trail to group fire ring is steep and brushy.	7	9	Paved and mostly striped with barrier rock around edges	Good	X	MDO on PTDF	Good	Located on along North Shore Recreation Facilities Access Road	1-1966	Good Surrounded by rock ring	7-1966	Poor to Fair. Old style benches. 5 located around group fire pit. 2 in kitchen across from small fire pit. People move them around the site.	6-2006	Good Heavy wood benches on steel posts set in ground	2-2002	Good	1	Small orregated steel fire ring in kitchen area with 2 benches on either side.	3-2002	Good 2 are set on concrete pads, the other is not	2-1999	Good Both are set on concrete pads	1	Good. Standard plastic can set between two bear-proof bins.	4	Good	7	Good Supposed to be 8 picnic tables but 1 is missing.	Site was recently used as a staging area by fire crews. Lots of stacked fire wood left by fire crews. Site was closed from June to mid-July during fire.
		0						17	26						3		17		16		5		1		9		8		2		13		19			

Notes:

- * - dimensions based on information provided by Ed Moore , TNF
- ** - number of units and year installed based on information provided by Ed Moore, TNF
- NA - Not applicable.
- HC - Handicap Accessible
- PTDF - Pressure Treated Douglas Fir
- AC - Asphaltic Concrete, otherwise known as asphalt or pavement
- AO - Asphalt Overlay - A top coat of AC applied to a previously paved surface.
- Chip seal - Oil and crushed rock (usually 1/4") applied over a previously paved surface
- Crushed rock - Clean (no fines) crushed rock, usually 1/4" or 3/4"
- Aggregate Base - A combination of crushed rock, sand and clay. The fines make aggregate base compactable.