

DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

SITE/UNIT FEATURES

| Site # | Host Site | Designated Accessible Site? | Accessibility Constraints | | | | Spur | | | | Site Signs | | | | | | Stoves, Grills, Fire Rings, Bear Boxes, and Garbage Cans | | | | | | | | | | | | Tables | | | | Other | | | | | | | | | | |
|-----------------------------------|-----------|-----------------------------|---------------------------|-----------|---------------------|---|---|-------------------|------------|---------------------------------------|-------------------|-------------------------|-------------------------|-----------|---------------|----------|--|---------------------------------------|-------------------|-------------------|---|-------------|--------------------------------|-------------|---|------------------------|---|----------|-------------------|------------------|--|--------------------|---|--------------|--|------------------------------|--|-----------------------------|--|---------|--|---|--|
| | | | Needs Leveling | Obstacles | Excessive Brush/Veg | Inadequate Clear Space | Remarks | RV | Regular | Material | Condition/Remarks | Site Marker | Material | Condition | Other Signage | Material | Condition | Concrete Stove w/ Steel Grill Stove** | Condition/Remarks | Group Fire Ring** | Condition/Remarks | Old Benches | Condition/Remarks | New Benches | Condition/Remarks | HC Double Ped. Grill** | Condition/Remarks | Fire Pit | Condition/Remarks | Large Bear Box** | Condition/Remarks | Bear-proof Garbage | Condition/Remarks | Garbage Cans | Condition/Remarks | Serving Table (Heavy Wood)** | Condition | Picnic Table (Heavy Wood)** | Condition | Remarks | | | |
| Ponderosa (75 person site) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | No | X | X | | X | Could be made accessible. Serving and picnic tables create obstacles. | 12 | 13 | Paved (AC) | Striped/Good | 1 | Painted Al on wood post | Good | None | | | | | 3-1966 | Set side by side. One is in good condition and the other two are damaged. | 1-1966 | Poor. Bent and improperly set. | 13 | Heavy wood. Fair to poor. Most are set too low and are crooked. One is broken. All need sanding and painting. | 7-2006 | Heavy wood on steel posts. Good condition. | 2-2001 | Good but rusty. | 1 | Located in center of camp. Poor condition. Bent and rusty. | 4-2001 | Good condition. Two are on concrete pads. | 3-1998 | Located near entrance, across from toilet. All on concrete pads. Good condition. | 1 | regular plastic trash can with stenciled "aluminum cans" on side | 4 | Good | 11 | Good | Concrete pad with wood post and ring next to faucet #1. | |
| Lodgepole 25 person site | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | No | | | | Relatively level and free of obstacles. | 4 + 1 turn-around | 5 | Paved (AC) | Striped/Good | 1 | Painted Al on wood post | Good | None | | | | | 2-1966 | Damaged. | 1-1966 | | | | | 5-2006 | Benches are wood on steel posts all in good condition | 1-2001 | Good | | | 2-2001 | Good condition. One is set on a concrete pad. | 2-1998 | Both on concrete pads. Good condition. | | | 3 | Good | 4 | Good | Two concrete pads with nothing on them. | |
| Aspen (25 person site) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | No | | | | Relatively level and free of obstacles. | 4 + 1 turn-around | 5 + 1 turn-around | Paved (AC) | Good but RV striping is criss crossed | 1 | Painted Al on wood post | Good | None | | | | | 2-1966 | | 1-1966 | | | | | 5-2006 | Benches are wood on steel posts all in good condition | 1-2001 | Good | | | 2-2001 | Good condition. One is on concrete pad. | 2-1998 | Both are in good condition but one is installed backwards. | | | 3 | All in good condition with exception of flaking paint. | 4 | All in good condition with exception of flaking paint. | One concrete pad next to bathroom. One concrete pad with wood post and steel ring in kitchen. | |
| | | 0 | | | | | | | | | 3 | | | | | | | | 7 | | 3 | | | | | 13 | | 17 | | 4 | | 1 | | 8 | | 7 | | 1 | | 10 | | 19 | |

Notes:
 * - dimensions based on information provided by Ed Moore , TNF
 ** - number of units and year installed based on information provided by Ed Moore, TNF
 NA - Not applicable.
 HC - Handicap Accessible
 PTDF - Pressure Treated Douglas Fir
 AC - Asphaltic Concrete, otherwise known as asphalt or pavement
 AO - Asphalt Overlay - A top coat of AC applied to a previously paved surface.
 Chip seal - Oil and crushed rock (usually 1/4") applied over a previously paved surface
 Crushed rock - Clean (no fines) crushed rock, usually 1/4" or 3/4"
 Aggregate Base - A combination of crushed rock, sand and clay. The fines make aggregate base compactable.