

**Appendix N-2**  
**Gates Group Campground**  
**Photographs**



**Photo N-2-1. Double swing gate at main entrance road to Gates Group Campground. (9/4/08)**



**Photo N-2-2. Signage at Gates Group Campground exit. (9/4/08)**



**Photo N-2-3. Main access road to Gates Group Campground. (9/4/08)**



**Photo N-2-4. Swing gate at entrance to Ponderosa. The gate at Ponderosa is a double gate and was installed in October 2007. (9/4/08)**



**Photo N-2-5. Swing gate along main access road near Aspen, looking north towards Lodgepole. This gate was installed in September 2006. (7/23/08)**



**Photo N-2-6. Typical campsite marker and carsonite water line marker. (9/4/08)**



**Photo N-2-7.** Typical parking area at Gates Group Campground. This parking area is located at the entrance to Ponderosa. Note the striping and long stalls for trailers/RVs. Pavement is in good condition. (9/4/08)



**Photo N-2-8.** Typical bear-proof garbage containers in the Gates Group Campground. These containers are located at the entrance to Ponderosa. (9/4/08)



**Photo N-2-9. Typical vault bathroom in Gates Group Campground. This bathroom is located in Ponderosa Campground. None of the bathrooms in the Gates Group Campground are accessible. (9/4/08)**



**Photo N-2-10. Ponderosa, a 75 person group camp. (9/4/08)**



**Photo N-2-11. Four bear-proof garbage containers (bear boxes) and a heavy wood serving table at Ponderosa. (9/4/08)**



**Photo N-2-12. Three concrete stoves with steel grills at Ponderosa. (9/4/08)**



**Photo N-2-13. Small fire pit in Ponderosa kitchen area. (9/4/08)**



**Photo N-2-14. Damaged group fire pit at Ponderosa. Note new benches in middle ground and old benches in background. (9/4/08)**



**Photo N-2-15. Turn-around area at Lodgepole. Note pavement is in good condition. (9/408)**



**Photo N-2-16. Group fire pit and new benches at Lodgepole. (9/4/08)**



**Photo N-2-17. Typical heavy wood picnic tables and water faucet in Gates Group Campground. This photograph was taken at Aspen. (9/4/08)**



**Photo N-2-18. Typical heavy wood serving tables and concrete stoves with steel grills in Gates Group Campground. This photograph was taken at Aspen. (9/4/08)**



**Photo N-2-19. Double, handicap accessible, steel, adjustable cooking grill. This photograph was taken at Aspen. (9/4/08)**



**Photo N-2-20. Group fire pit and new benches at Aspen. (9/4/08)**