

Appendix P-2
McGuire Boat Ramp
Photographs



Photo P-2-1. McGuire Boat Ramp on July 23, 2008 (WSE = 5,220 ft).



Photo P-2-2. View of McGuire Boat Ramp from top of ramp. (7/23/08)



Photo P-2-3. High water turn-around and loading/unloading area. Note “no parking” sign and graffiti on surface. (7/23/08)



Photo P-2-4. Uplifted concrete at edge of high water turn-around area. (7/23/08)

McGuire Boat Ramp Parking Areas



Photo P-2-5. Entrance to McGuire Boat Ramp Parking Area – southeast lot. Note transition from asphalt pavement access road to base rock in parking area. (7/23/08)



Photo P-2-6. McGuire Boat Ramp Parking Area – southeast lot. Surface has deteriorated to base rock and is in poor condition. (7/23/08)



Photo P-2-7. Sign and post and cable barrier fence along north side of McGuire Boat Ramp Parking Area southeast lot. (7/23/08)



Photo P-2-8. North entrance to McGuire Boat Ramp Parking Area – northeast lot. Note transition from asphalt pavement access road to base rock in parking area. (7/23/08)



Photo P-2-9. South entrance to McGuire Boat Ramp Parking Area – northeast lot. Surface has deteriorated to base rock and is in poor condition. (7/23/08)



Photo P-2-10. Sign along access road near McGuire Boat Ramp Parking Area – between northeast and southeast lots. (7/23/08)