

Appendix Q-2
McGuire Beach, Picnic Area, and Associated Parking Areas
Photographs



Photo Q-2-1. Site identification sign at entrance to McGuire Picnic Area. (7/24/09)



Photo Q-2-2. Gated entrance and access road to McGuire Picnic Area, beach, and parking area. (7/24/08)



Photo Q-2-3. Potholes and damaged pavement along access road to McGuire Picnic Area, beach, and parking area. (7/24/08)



Photo Q-2-4. McGuire Picnic Area and Beach parking area. Note deteriorated asphalt surface. (7/24/08)



Photo Q-2-5. Gate blocking access to old service road. (7/24/08)



Photo Q-2-6. Bathroom located adjacent to parking area. Not disabled accessible. (7/24/08)



Photo Q-2-7. Typical picnic site at McGuire Picnic Area (Site 1). Note heavy wood table and concrete/steel cooking grill. Features are not disabled accessible, nor is the site due to obstacles (brush and rocks) and level changes. (7/23/08)



Photo Q-2-8. Overgrown picnic site at McGuire Picnic Area. Dense vegetation is due to lack of use and poor maintenance. (7/24/08)



Photo Q-2-9. Entrance of trail to McGuire Beach as viewed from the parking area. Note bear-proof garbage container, information board, and deteriorated asphalt surface. (7/24/08)



Photo Q-2-10. Trail to McGuire Beach, passing bathroom and changing area. (7/24/08)



Photo Q-2-11. Backside of bathroom building. Space behind blue doors is now used for storage. Concrete pad was formerly a changing area. Note damage on building and large lip on concrete pad. (7/24/08)



Photo Q-2-12. Water faucet located along path to McGuire Beach, near bathroom. Handle is accessible but approach is not because the sump/drain is set above grade. (7/24/08)



Photo Q-2-13. Trail to McGuire Beach with sign. (7/24/08)



Photo Q-2-14. McGuire Beach on July 24, 2008 (WSE = 5,220 ft).