

Appendix R-2
Middle Meadows Group Campground
Photographs



Photo R-2-1. Site Identification Sign and Visitor Message Post located on Eleven Pines Road (FR-2). (8/21/08)



Photo R-2-2. Gate at entrance to Middle Meadows Campground Access Road (14N28). (8/21/08)



Photo R-2-3. Example of poor condition pavement along Middle Meadows Campground Access Road (14N28). (8/2108)



Photo R-2-4. Ford across South Fork Long Canyon Creek. (8/21/08)



Photo R-2-5. Parking for Unit 1. (8/21/08)



Photo R-2-6. Fee station located adjacent to parking for Unit 1. (8/21/08)



Photo R-2-7. Information boards along pathway (service road) to Unit 1. (8/21/08)



Photo R-2-8. Double unit accessible bathroom with flush toilets located at Unit 1. (8/21/08)



Photo R-2-9. Accessible group fire ring at Unit 1. (8/21/08)



Photo R-2-10. Accessible picnic table at Unit 1. (8/21/08)



Photo R-2-11. Kitchen area in Unit 1. Note accessible double pedestal grill, bear box on concrete pad, and new serving tables. (8/21/08)



Photo R-2-12. Older picnic tables at Unit 1. All are in fair condition, with peeling paint and cracks. This one is in poor condition due to damage bench. (8/21/08)



Photo R-2-13. Parking for Unit 2.



Photo R-2-14. Single unit accessible vault toilet along pathway to Unit 2. (8/21/08)



Photo R-2-15. Unit 2. (8/21/08)



Photo R-2-16. Kitchen area of Unit 2. (8/21/08)



Photo R-2-17. Group fire pit with grill at Unit 2. Note heavy wood benches. (8/21/08)



Photo R-2-18. Double accessible picnic table at Unit 2. Heavy wood bench in foreground. (8/21/08)



Photo R-2-19. Accessible faucet at Unit 2. (8/21/08)