

Appendix S-2
Ralston Picnic Area and Cartop Boat Ramp
Photographs



Photo S-2-1. Site Identification sign and other signs at entrance to Ralston Picnic Area. (7/23/08)



Photo S-2-2. Entrance to Ralston Picnic Area and Car Top Boat Ramp. (7/23/08)



Photo S-2-3. Parking area and entrance road as viewed from bathroom. (7/23/08)



Photo S-2-4. Single unit, pre-fabricated concrete toilet (CXT) at Ralston Picnic Area. (7/23/08)



Photo S-2-5. Typical picnic sites at Ralston Picnic Area (Site 4 in foreground, Site 3 in background). These sites are not considered disabled accessible due to insufficient clear space, obstacles, and level changes. In addition, the tables and grills are not accessible.



Photo S-2-6. Site 5 picnic table. Table is in poor condition and does not meet accessibility standards.




Photo S-2-7. Trail to Site 5 near the Middle Fork American River. (7/23/08)



Photo S-2-8. Ralston Car Top Boat Ramp on November 12, 2008 at 10:33 A.M. This photograph was taken during PCWA's annual maintenance outage when the reservoir WSE was about 1,155 feet. Note the large rock in center of ramp.



Photo S-2-9. Close up of Ralston Car Top Boat Ramp Note large rock in center of ramp. (7/23/08)



Photo S-2-10. Sediment removal access point on Ralston Afterbay. This site is not a Project recreation facility but is sometimes used to access the reservoir. (11/12/08)