

**Appendix T-2**  
**Indian Bar Rafter Access**  
**Photographs**



**Photo T-2-1. Unloading area at Indian Bar Rafter Put-in as viewed from access road. The boat launch ramp is located in the background, adjacent to the bathroom. (7/23/08)**



**Photo T-2-2. Barrier rock delineating unloading area at Indian Bar Rafter Put in. (7/23/08)**



**Photo T-2-3. Designated parking area located south of the unloading area. (7/23/08)**



**Photo T-2-4. Boat launch ramp. Note warning sign and bear proof garbage to right of ramp. (7/23/08)**



**Photo T-2-5. Warning sign adjacent to boat launch ramp. (7/21/08)**



**Photo T-2-6. Single unit accessible CXT adjacent to boat launch ramp.**



**Photo T-2-7. Double unit accessible CXT and bear-proof garbage adjacent to parking area. (7/23/08)**



**Photo T-2-8. Double unit accessible CXT upslope from parking area. (7/23/08)**



**Photo T-2-9. Damaged information board adjacent to CXT upslope from parking area. (7/23/08)**



**Photo T-2-10. Good condition information board adjacent to boat launch ramp. (7/23/08)**