DEVELOPED RECREATION FACILITY INVENTORY AND ACCESSIBILITY FORM

SITE/UNIT FEATURES

			Accessibility Constraints					Spur				Site Signs						Stoves, Grills, Fire Rings and Bear Boxes												Tables					Other
Site #	Host Site	Designated Accessible Site?	Needs Leveling	Obstacles	Excessive Brush/Veg	Adequate Clear Space	Remarks	Size	Material	Condition	Remarks	Site Marker	Material	Condition	Other Signage	Material	Condition	Concrete Stove	Steel Stove	Steel Fire Ring	Fire Ring with Steel Grill	HC Fire Ring with Adj. Grill	Ped. Grill	HC Ped Grill	Double Ped. Grill	HC Double Ped Grill	Bear Box	Condition	Remarks	Wood Table (Light)	Wood Table (Heavy)	HC Table (light)	HC Double Table (light)	Condition	Remarks	Remarks
1		No	No	No	No	Yes	Site is entirely accessible but is not designated as handicap accessible. *Needs minor leveling.	NA	NA	NA	Walk-in site	X	PTDF	Good								1					1	Good/ Good	Fire ring is rusted.			1		Good	Wood planks on steel base	Accessible path from Site 1 to parking area.
2		No	Yes	Yes	Yes	No	Accessible path to site.	NA	NA	NA	Walk-in site	X	PTDF	Good								1					1	Good/ Good	Fire ring is rusted.		1			Good		Hazard trees present. Accessible path from Site 2 to parking area.
3		No	No	No	No	Yes	Accessible path to site.	NA	NA	NA	Walk-in site	X	PTDF	Good								1					1	Good/ Good	Fire ring is rusted.		1			Good		Accessible path from Site 3 to parking area.
4		No	Yes	Yes	Yes	No	Needs minor leveling. Access to site is difficult	NA	NA	NA	Walk-in site	X	PTDF	Good				1				1					1	Poor/ Good/ Good	Concrete stove is damaged and in poor condition. Fire ring is surrounded in boulders that should be removed.		1			Good		
5		No	No	No	No	No	Needs minor leveling. Access to site is difficult	NA	NA	NA	Walk-in site	X	PTDF	Good								1					0	Good	Bear box is in good condition. Fire ring is rusted.		1			Fair	Paint is flaking.	
6		No	No	No	No	Yes	Needs minor leveling. Access to site is difficult	NA	NA	NA	Walk-in site	X	PTDF	Good				1				1					0	Good/ Good	Fire ring is rusted.	1	1			Good	Light table is wood plank on steel base.	
7		No	Yes	Yes	No	No	Obstacles present. Needs minor leveling. Access to site is difficult.	NA	NA	NA	Walk-in site	X	PTDF	Good								1					0	Good*	Fire ring is in good condition but is sitting on rocks. Needs to be reset.		1			Fair		Paint is flaking.
8		No	No	Yes	No	Yes	Needs minor leveling. Could be made accessible - Gentle slope, not many obstacles.	NA	NA	NA	Walk-in site	X	PTDF	Good				1				0					1	Good/ Good			1			Good		
9		No	No	Yes	No	Yes	Needs minor leveling. Could be made accessible - Gentle slope, not many obstacles.	NA	NA	NA	Walk-in site	X	PTDF	Good								1					1	Good			1			Fair		Table is functional but in need of new paint. Benches are cracked.
10		No	No	Yes	No	Yes	Needs minor leveling. Could be made accessible - Gentle slope, not many obstacles.	NA	NA	NA	Walk-in site	X	PTDF	Good								1					1	Good			1			Good		
		0										**10**						**3**				**9**					**7**			**1**	**9**	**1**				

Notes:

NA - Not applicable.
HC - Handicap Accessible
PTDF - Pressure Treated Doulas Fire
AC - Asphaltic Concrete, otherwise known as asphalt or pavement
AO - Asphalt Overlay - A top coat of AC applied to a previously paved surface.
Chip seal - Oil and crushed rock (usually 1/4") applied over a previously paved surface
Crushed rock - Clean (no fines) crushed rock, usually 1/4" or 3/4"
Aggregate Base - A combination of crushed rock, sand and clay. The fines make aggregate base compactable.